Model 522 Installation Instructions

1. Package Contents:

1 Mechanical Scale

1 Upper Hook

1 Lower Hook

2. Installation

Hang scale with hooks aligned as shown in picture

3. Adjust Zero

Turn Zero adjustment knob until dial reaches an exact zero.

Your scale is now ready to use!

Scalesco Measurement Technology Inc.

1200 Indus Street Suite A, Fairmont MN 56031
(Toll Free) 866-587-9773 (Phone) 507-238-9773 (Fax) 507-238-5447
(Web-site) http://www.scales-co.com (E-mail) sales@scales-co.com